

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** CF-2020-05 - VIKING AIR LTD: Wings – Cracking and Corrosion of Aileron Internal Structure

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/CF-2020-05>

* **EAD** 2020-0062-E - LEONARDO S.p.A. HELICOPTERS: Tail Rotor – Hub / Blade Assembly – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:

<https://ad.easa.europa.eu/ad/2020-0062-E>
