

Occurrence Communication: Oc00064-2020 **Date:** 04/Mar/2020

Page 1 of 1

Type: /

Aircraft: EMB-145	Model: EMB-145 LR	Serial Number: 145906
Marks: N922AE	Operator: ENVOY	Occurence Date: 21/Sep/2019
Ata: 21	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: TAMPA INTL - TAMPA - FL - UNITED STATES		
Injuries: <input checked="" type="checkbox"/> None Light: 0 Serious: 0 Fatal: 0		

Occurrence Description:

Report of vibration and smoke in the cabin
 IN CRUISE FLT FL240, FA REPORTED SMOKE IN THE CABIN, FOLLOWED AOM EMERGENCY PRECEDURES, LANDED SAFELY IN TPA. UPON CABIN INSPECTION FOUND SMOKE MARKS BY SEATS 4C, 5C. FA REPORTS SMOKE CAME OUT BY SEATS 3A, 4A. PAX REPORTS VIBRATION BY SEAT 11A. C/A- DURING INSPECTION OF #2 PACK FOUND ACM NOT TURNING. REMOVED AND REPLACED ACM OPS CHECK GOOD IAW AMM 21-51-03. NO SMOKE IN THE CABIN NOTED.