

## **EMBRAER S.A.**

Model:

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901

Serial Number:

Phone: +55 12 3313-2568 Fax: +55 12 3313-1184

Occurrence Communication: Oc00071-2020 Date: 09/Mar/2020 Page 1 of 1

Type: /

Aircraft:

Report of smoke The flight crew reported electrical fumes on arrival.  Maintenance personnel removed and replaced the recirculation fan 1 IAW AMM 145 21-24-01. Subsequent					
N670AE ENVOY 04/Mar/2020  Ata: 21 Time: Number of Persons Aboard: Not Available  Aircraft Damages:  Site: DALLAS-FT WORTH INTL - DALLAS-FT WORTH - TX - UNITED STATES  Injuries: X None Light: Serious: Fatal: 0  Occurence Description:  Report of smoke The flight crew reported electrical fumes on arrival.  Maintenance personnel removed and replaced the recirculation fan 1 IAW AMM 145 21-24-01. Subsequent	EMB-145	EMB-14	15 LR		145790
Ata: 21  Time:  Number of Persons Aboard: Not Available  Aircraft Damages:  Site: DALLAS-FT WORTH INTL - DALLAS-FT WORTH - TX - UNITED STATES  Injuries: X None Light: 0 Serious: 0 Fatal: 0  Occurence Description:  Report of smoke The flight crew reported electrical fumes on arrival.  Maintenance personnel removed and replaced the recirculation fan 1 IAW AMM 145 21-24-01. Subsequent	Marks:	Operate	or:		Occurence Date:
Aircraft Damages:  Site: DALLAS-FT WORTH INTL - DALLAS-FT WORTH - TX - UNITED STATES  Injuries: X None Light: 0 Serious: 0 Fatal: 0  Occurence Description:  Report of smoke The flight crew reported electrical fumes on arrival.  Maintenance personnel removed and replaced the recirculation fan 1 IAW AMM 145 21-24-01. Subsequent	N670AE	ENVOY	,		04/Mar/2020
Site:  DALLAS-FT WORTH INTL - DALLAS-FT WORTH - TX - UNITED STATES  Injuries: X None Light: 0 Serious: 0 Fatal: 0  Occurence Description:  Report of smoke The flight crew reported electrical fumes on arrival.  Maintenance personnel removed and replaced the recirculation fan 1 IAW AMM 145 21-24-01. Subsequent	Ata: 21	Time:			
DALLAS-FT WORTH INTL - DALLAS-FT WORTH - TX - UNITED STATES  Injuries: X None Light: 0 Serious: 0 Fatal: 0  Occurence Description:  Report of smoke The flight crew reported electrical fumes on arrival.  Maintenance personnel removed and replaced the recirculation fan 1 IAW AMM 145 21-24-01. Subsequent	Aircraft Damages:				
DALLAS-FT WORTH INTL - DALLAS-FT WORTH - TX - UNITED STATES  Injuries: X None Light: 0 Serious: 0 Fatal: 0  Occurence Description:  Report of smoke The flight crew reported electrical fumes on arrival.  Maintenance personnel removed and replaced the recirculation fan 1 IAW AMM 145 21-24-01. Subsequent	Site				
Occurence Description:  Report of smoke	I .	DALLAS-FT WC	ORTH - TX - UNITED	STATES	
Report of smoke The flight crew reported electrical fumes on arrival.  Maintenance personnel removed and replaced the recirculation fan 1 IAW AMM 145 21-24-01. Subsequent	Injuries: X None I	Light: 0	Serious: 0	Fatal:	0
The flight crew reported electrical fumes on arrival.  Maintenance personnel removed and replaced the recirculation fan 1 IAW AMM 145 21-24-01. Subsequent	Occurence Description:				
	The flight crew reported electric Maintenance personnel rem	noved and replaced		1 IAW AMM 1	45 21-24-01. Subsequent