

**Occurrence Communication:** Oc00072-2020**Date:** 10/Mar/2020

Page 1 of 1

**Type:** /

<b>Aircraft:</b> EMB-145	<b>Model:</b> EMB-135 ER	<b>Serial Number:</b> 145198
<b>Marks:</b> 5N-BSN	<b>Operator:</b> BRISTOW NIGERIA	<b>Occurrence Date:</b> 09/Mar/2020
<b>Ata:</b> 72	<b>Time:</b>	<b>Number of Persons Aboard:</b> Not Available
<b>Aircraft Damages:</b>		
<b>Site:</b> Port Harcourt Intl, Port Hartcourt Nigeria		
<b>Injuries:</b> <input checked="" type="checkbox"/> None <b>Light:</b> 0 <b>Serious:</b> 0 <b>Fatal:</b> 0		

**Occurrence Description:**

Report of uncommanded engine 1 IFSD after takeoff

The flight crew reported an audible indication from the LH engine, followed by an uncommanded IFSD shortly after takeoff while climbing through 300 feet. They then elected to return to the departure airport where they performed an uneventful single engine landing.

Maintenance personnel found fan seized and metal in the exhaust. The engine was removed and replaced.