

Occurrence Communication: Oc00077-2020 **Date:** 16/Mar/2020

Page 1 of 1

Type: /

Aircraft: EMB-145	Model: EMB-135 LR	Serial Number: 145551
Marks: ZS-SNV	Operator: AIRLINK	Occurrence Date: 23/Feb/2020
Ata: 72	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: Johannesburg Intl, Johannesburg South Africa		
Injuries: <input checked="" type="checkbox"/> None Light: 0 Serious: 0 Fatal: 0		

Occurrence Description:

UPDATE OF OCCURENCE Oc00058-2020:

Report of commanded IFSD due to loss of oil indication
 The flight crew reported loss of oil indication. They performed a precautionary right-hand engine shut down and uneventful single engine landing at destination airport.

ADDITIONAL INFORMATION:

As per Rolls Royce report, maintenance crew traced the oil leak back to the aircraft fire harness that was rubbing and chaffing the oil pressure tube on the oil pump, The customer confirmed that the fire wire was routed incorrectly.
 Rolls Royce has been closed this event NON-BASIC due to a maintenance error in routing the fire wire incorrectly.