

Occurrence Communication: Oc00120-2020 **Date:** 13/Jul/2020

Page 1 of 1

Type: /

Aircraft: EMB-145	Model: EMB-145 XR	Serial Number: 145657
Marks: N11109	Operator: EXPRESSJET	Occurrence Date: 15/Dec/2019
Ata: 22	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: NOT AVAILABLE		
Injuries: <input checked="" type="checkbox"/> None Light: 0 Serious: 0 Fatal: 0		

Occurrence Description:

Report of abnormal vibration in the yoke during cruise
The flight crew reported abnormal vibration in the yoke during cruise at FL360 and .70 mach. They reportedly slowed the aircraft to .65 mach and the vibration continued. They then diverted to the nearest suitable airport.

Maintenance personnel removed and replaced the autopilot elevator servo. Subsequent operational check was satisfactory.