

**Occurrence Communication:** Oc00128-2020**Date:** 16/Jul/2020

Page 1 of 1

**Type: Ground Occurrence**

<b>Aircraft:</b> EMB-145	<b>Model:</b> EMB-145 LR	<b>Serial Number:</b> 145241
<b>Marks:</b> XA-IFP	<b>Operator:</b> TAR	<b>Occurrence Date:</b> 16/Jul/2020
<b>Ata:</b> 00	<b>Time:</b>	<b>Number of Persons Aboard:</b> Not Available
<b>Aircraft Damages:</b> The aircraft was hit in the right wing trailing edge.		
<b>Site:</b> ING F. ESPINOZA GUTIERREZ INTL - QUERETARO - MEXICO		
<b>Injuries:</b> <input checked="" type="checkbox"/> None <b>Light:</b> 0 <b>Serious:</b> 0 <b>Fatal:</b> 0		

**Occurrence Description:**

Report of collision with aircraft while parked during a thunderstorm  
It was reported that the aircraft, while parked in the apron, was struck in its the right wing trailing edge by another aircraft which was moved due to wind gusts during a thunderstorm.