

EMBRAER S.A.

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901

Phone: +55 12 3313-2568 Fax: +55 12 3313-1184

Occurrence Communication: Oc00141-2020 Date: 15/Aug/2020 Page 1 of 1

Type: /

Aircraft:	Model:	Serial Number:
EMB-145	EMB-145 XR	145714
Marks:	Operator:	Occurence Date:
N25134	EXPRESSJET	12/Aug/2020
Ata : 72	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: AMARILLO INTL - AMARILLO - TX - UNITED STATES		
Injuries: X None Light:	O Serious: O Fatal:	0

Occurence Description:

Report of precautionary engine 2 IFSD during flight
The flight crew reported engine 2 high ITT indication followed by abnormal vibration indication for engine 2.
Reportedly, as the vibration indication increased, the flight crew elected to shut down the engine 2 and return to the departure airport.