

Occurrence Communication: Oc00166-2020**Date:** 02/Oct/2020

Page 1 of 1

Type: /

Aircraft: EMB-145	Model: EMB-135 BJ	Serial Number: 1451106
Marks: N106EC	Operator: PRIVATE OPERATOR	Occurrence Date: 23/Sep/2020
Ata: 27	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: SELETAR - SINGAPORE - SINGAPORE		
Injuries: <input checked="" type="checkbox"/> None Light: 0 Serious: 0 Fatal: 0		

Occurrence Description:

Report of abnormal vibration in the yoke during cruise
The flight crew reported abnormal vibration in the control column during cruise.

Maintenance personnel found the elevator control cables tension over the limit. The control cables tension was adjusted.