

## **EMBRAER S.A.**

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901

Phone: +55 12 3313-2568 Fax: +55 12 3313-1184

Occurrence Communication: Oc00169-2020 Date: 21/Oct/2020 Page 1 of 1

Type: /

Aircraft:	Model:	Serial Number:
EMB-145	EMB-145 XR	145735
Marks:	Operator:	Occurence Date:
N12142	EXPRESSJET	12/Sep/2020
Ata: 33	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: BIRMINGHAM INTL - BIRMINGHAM - AL - UNITED STATES		
Injuries: X None Light:	0 Serious: 0 F	Fatal: 0
Occurence Description:		
Report of smoke on sidewall light panel during flight Flight crew reported smell of smoke and visible smoke were on the sidewall light panel 20A with visible burn mark. The aircraft landed without incident.		
Maintenance personnel inspected the aircraft, deactivated the light assembly at seat 20A and dispatched on MEL.		