

FAKT AD 2.1 - 1

AD 2 AERODROMES

FAKT AD 2.1 Aerodrome Location Indicator And Name FAKT - BOSCHKOP (Kitty Hawk Aero Estate (200)

FAKT AD 2.2 Aerodrome Geographical And Administrative Data

1	ARP Coordinates and site at AD	Ref. Point: S255142 E0282649		
2	Direction and distance from city	14,5 km E of Wapadrand		
3	Elevation / Reference temperature	Elev: 4586 FT		
4	MAG VAR / Annual change			
5	AD operator, address, telephone, telefax, email, AFS address and, if available, website address	PUB AD CHF: KITTY HAWK BODY CORP. P O Box 2178, ZWAVELPOORT, 0036. TEL: 012 809 0942 FAX: (012) 809 0608 Email: office@kitty-hawk.co.za VHF: 120,65 MHz		

FAKT AD 2.3 Operational Hours

		SR-SS: 078 003 1121
8	Fuelling	Emergency: 083 334 4714

FAKT AD 2.4 Handling Services And Facilities

		AVGAS 100LL
2	Fuel/()il types	OIL : W100,
		Supplier: BP Tel: 8110408

FAKT AD 2.12 Runway Physical Characteristics

Designations RWY NR	TRUE & MAG BRG	Dimensions of RWY (M)	Strength (PCN) and surface of RWY and SWY	THR coordinates	THR elevation and highest elevation of TDZ of precision APP RWY
1	2	3	4	5	6
<u>01</u> 19	0 <u>14</u> 194	810 x 18	ASPH ACFT Ltd strength 3,5 tons.		

Civil Aviation Authority



FAKT AD 2.20 - 2

FAKT AD 2.12 Runway Physical Characteristics

Designations RWY	Slope of	SWY dimensions	CWY dimensions	Strip dimensions	
NR	RWY-SWY	(M)	(M)	(M)	OFZ
1	7	8	9	10	11
<u>01</u> 19	140 - 600M in 1.9 % 600 - 870M in 1% 870 - 1035M in 0.8% Safe approach slope on 3 °				
Remarks Powerlines 2000 metres south of the aerodrome Marked powerline on final approach RWY 19.					

FAKT AD 2.20 Local Traffic Regulations

- (1) Runway 01 Right hand circuits
- (2) Runway 19 Left hand circuits.
- (3) Pilots to broadcast their intentions on 120,65 MHz Kitty Hawk Traffic when east of the Waterkloof CTR.
- (4) Join overhead 6100 FT
- (5) APCH 01- Be aware of turbulence and down drafts/wind shear.
- (6) Keep look out for guinea fowl and bucks at times.
- (7) Occasional aerobatic practice on the western side.
- (8) Helicopter parking marked H on the northern side of the aerodrome.
- (9) Poor radio communication between holding point RWY 01 and 19 at times.
- (10) APCH RWY 01 with crosswind from west- suggest deep landing where possible.

Civil Aviation Authority