

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD US-2015-19-12** - BOEING: SUPERSEDED BY FAA AD 2018-07-18

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2015-19-12>

* **AD 2017-0064R2** - SAFRAN HELICOPTER ENGINES: Engine Fuel & Control – Drain Valve Assembly – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0064R2>

* **AD 2018-0084R1** - ROLLS-ROYCE PLC: Engine – Intermediate Pressure Compressor Blades / Shaft – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0084R1>

* **AD US-2018-06-07** - BOEING: Fuselage - Fuselage Frame - Repetitive Inspections / Repair

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2018-06-07>

* **AD US-2018-07-18** - BOEING: Fuselage - Stringer Lap Splices - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2018-07-18>