

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2016-0253** - AIRBUS: SUPERSEDED BY EASA AD 2018-0097

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2016-0253>

* **AD 2017-0173** - AIRBUS: SUPERSEDED BY EASA AD 2018-0098

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0173>

* **AD 2018-0099** - AIRBUS: Fuel – Trim Tank Vent Pipes – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0099>

* **AD 2018-0097** - AIRBUS: Time Limits / Maintenance Checks – Damage Tolerant Airworthiness Limitation Items – ALS Part 2 – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0097>

* **AD 2018-0098** - AIRBUS: Time Limits / Maintenance Checks – Airworthiness Limitations Section – Part 3 – Certification Maintenance Requirements – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0098>

* **AD 2018-0096** - AIRBUS: Time Limits / Maintenance Checks – Safe Life Airworthiness Limitations Items – ALS Part 1 – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0096>

* **AD 2018-0095** - ROLLS-ROYCE PLC: Engine – Intermediate Pressure Compressor Rotor Seal – Inspection / De-Pairing Limitation

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0095>