

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD 2018-0076** - FOKKER SERVICES: Landing Gear – Hydraulic Line T-Union – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0076>

---

\* **AD 2018-0077** - FOKKER SERVICES: Landing Gear – Hydraulic Line Restrictor Check Valve – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0077>