

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2018-0174** - AIRBUS: Wings – Top Skin Stringer Joints at Rib 19 – Inspection / Modification

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0174>
