

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2018-0176** - AIRBUS HELICOPTERS: Main Rotor Drive – Main Gearbox Magnetic Plug – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0176>

* **AD 2018-0177** - AIRBUS HELICOPTERS: Rotor Drive – Main Gearbox Magnetic Plugs – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0177>

* **AD US-2018-17-04** - ROLLS-ROYCE CORPORATION (USA): Engine - Turbine Wheels - Removal / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2018-17-04>

IMPORTANT NOTICE

The 6th EASA Airworthiness Directives (AD) Workshop will be held on **20-21 November 2018** in Cologne.

The event is addressed to all interested stakeholders such as operators, CAMO, maintenance organisations, design approval holders, who want to have a better understanding of EASA processes related to safety publications.

More information, agenda and online registration are available [here](#).

EASA Safety Information Section