The following Documents have been published or updated by EASA and may be of interest to you:

\* **PAD** 18-113 - AIRBUS: Hydraulic System / Fuel Tank Inerting System – Engine Driven Pump Rapid Overheat – Master Minimum Equipment List Restriction / Software Update / Modification

TO see the details OF this Publication, please click OR copy the following: URL: <u>http://ad.easa.europa.eu/ad/18-113</u>

\* **PAD** 18-114 - AIRBUS: Time Limits / Maintenance Checks – Certification Maintenance Requirements – ALS Part 3 – Amendment

TO see the details OF this Publication, please click OR copy the following: URL: <u>http://ad.easa.europa.eu/ad/18-114</u>