

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** US-2004-26-09 - ROLLS-ROYCE CORPORATION (USA): Engine - Compressor Adaptor Couplings - Identification / Replacement / Removal from Service

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2004-26-09>

* **AD** 2017-0241 - ROLLS-ROYCE PLC: SUPERSEDED BY EASA AD 2018-0188

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0241>

* **AD** 2017-0257R1 - AIRBUS: SUPERSEDED BY EASA AD 2018-0189

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0257R1>

* **AD** 2018-0189 - AIRBUS: Navigation – Back Up Speed Scale / Aircraft Flight Manual – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0189>

* **AD** 2018-0188 - ROLLS-ROYCE PLC: Engine – Low Pressure Compressor Blades – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0188>

IMPORTANT NOTICE

The 6th EASA Airworthiness Directives (AD) Workshop will be held on **20-21 November 2018** in Cologne.

The event is addressed to all interested stakeholders such as operators, CAMO, maintenance organisations, design approval holders, who want to have a better understanding of EASA processes related to safety publications.

More information, agenda and online registration are available [here](#).

EASA Safety Information Section

