

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD** CF-2018-20 - BOMBARDIER: Landing Gear – Main Landing Gear Side Brace Actuators Contain Non-Conforming Split Ball Bearing

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/CF-2018-20>

---

\* **AD** US-2018-15-06 - HONDA AIRCRAFT COMPANY LLC: Time Limits - Airworthiness Limitations - Revision

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/US-2018-15-06>