

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD** US-2018-23-51 - BOEING: [Correction] [Final Rule] Airplane Flight Manual - Runaway Horizontal Stabilizer Trim Limitations / Procedures - Amendment

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/US-2018-23-51>

---

\* **AD** 2018-0270 - LEONARDO S.p.A. HELICOPTERS: Windows – Passenger Windows – Repair

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0270>

---

\* **AD** 2018-0271 - AIRBUS: Equipment / Furnishings – Baby Bassinet Inserts – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0271>