

Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD 2012-0252** - AIRBUS HELICOPTERS: SUPERSEDED BY EASA AD 2017-0035

TO see the details OF this Publication, please click OR copy the following: URL:

<http://ad.easa.europa.eu/ad/2012-0252>

---

\* **AD 2017-0034** - TECHNIFY MOTORS: Engine – Gearbox – Modification / Inspection

TO see the details OF this Publication, please click OR copy the following: URL:

<http://ad.easa.europa.eu/ad/2017-0034>

---

\* **AD 2017-0035** - AIRBUS HELICOPTERS: Rotor Flight Controls – Twist Grip Assembly – Adjustment / Functional Check / Replacement / Modification

TO see the details OF this Publication, please click OR copy the following: URL:

<http://ad.easa.europa.eu/ad/2017-0035>

---

\* **AD 2017-0032** - AIRBUS HELICOPTERS: [Correction] Main Rotor – Main Rotor Hub / Mast Attachment Screws – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:

<http://ad.easa.europa.eu/ad/2017-0032>