

Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD US-2005-13-30** - BOEING: SUPERSEDED BY FAA AD 2017-02-02

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2005-13-30>

* **AD US-2017-01-09** - BOEING: [Correction] Air Conditioning - Flight Deck Display Units - Modification

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2017-01-09>

* **AD 2017-0033** - SAAB AB, AERONAUTICS: Time Limits / Maintenance Checks – Airworthiness Limitations Section – Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0033>

* **AD US-2017-02-02** - BOEING: Fuselage - Skin Panels - Inspection / Repair / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2017-02-02>

* **AD 2017-0032** - AIRBUS HELICOPTERS: Main Rotor – Main Rotor Hub / Mast Attachment Screws – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0032>