

The Civil Aviation Safety Authority has published the following urgent Airworthiness Directives:

[Airbus Helicopters Deutschland \(Eurocopter\) MBB-BK 117 Series Helicopters](#)

[2017-0037](#) - Main Rotor Drive - Rotor Mast Nut and Helical Gear Support - Re-identification

[Cessna 560 \(Citation V\) Series Aeroplanes](#)

[2017-04-14](#) - Alternating Current (AC) Generator Wire Bundle Chafing

[Safran Helicopter Engines \(Turbomeca\) Turbine Engines - Arriel Series](#)

[2017-0019R1](#) - Engine Fuel & Control - Drain Valve Assembly - Inspection / Replacement

These, and other Airworthiness Directives can be viewed at:

<https://www.casa.gov.au/airworthiness/standard-page/airworthiness-directives>

--

To update your preferences and to unsubscribe visit [this link](#)

Forward a Message to Someone [this link](#)

POWERED BY [PHPLIST](#)

Email secured by Check Point