

Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2017-0037** - AIRBUS HELICOPTERS DEUTSCHLAND: Main Rotor Drive – Rotor Mast Nut and Helical Gear Support – Re-identification

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0037>

* **AD 2017-0038** - AIRBUS HELICOPTERS DEUTSCHLAND: Rotors Flight Control – Cable Cut Flip Guard – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0038>

* **AD 2017-0019R1** - SAFRAN HELICOPTER ENGINES: Engine Fuel & Control – Drain Valve Assembly – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0019R1>

* **AD US-2017-04-14** - TEXTRON AVIATION INC.: Electrical Power - Fuel Tube and Right Alternating Current (AC) Generator Wires - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2017-04-14>
