

Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** US-2007-11-13 - BOEING: SUPERSEDED BY FAA AD 2017-01-03

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2007-11-13>

* **AD** 2015-0038R1 - AIRBUS: Powerplant – Forward Engine Mount – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2015-0038R1>

* **SIB** 2016-14R1 - Safety Information Bulletin: WITHDRAWN - REPLACED BY EASA SIB 2017-01

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2016-14R1>

* **PAD** 17-021 - AIRBUS: Fuel – Fuel Pump Canister Hood – Inspection / Replacement / Modification

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/17-021>

* **SIB** 2017-01 - Safety Information Bulletin: Safety Precautions regarding the Transport by Air of Damaged, Defective or Recalled Lithium Batteries

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-01>

* **AD** US-2017-01-03 - BOEING: Standard Practices/Structures - Airworthiness Limitations Section (ALS) of the Instructions for Continued Airworthiness - Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2017-01-03>