The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** 2018-0008 - AIRBUS: Wings – Main Landing Gear Trunnion Block Fuse Pin Retaining Pins – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/2018-0008

* **AD** 2017-0256 - LEONARDO S.p.A. HELICOPTERS: SUPERSEDED BY EASA AD 2018-0006

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/2017-0256

* CZIB CZIB-2018-01 - Conflict Zone Information Bulletin: Airspace of Saudi Arabia – Jeddah Flight Information Region - Valid until 09 July 2018

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/CZIB-2018-01

* CZIB CZIB-2018-02 - Conflict Zone Information Bulletin: Airspace of Pakistan – Karachi and Lahore Flight Information Regions - Valid until 09 July 2018

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/CZIB-2018-02

* **AD** 2018-0006 - LEONARDO S.p.A. HELICOPTERS: Equipment & Furnishings – Emergency Flotation System – Inspection

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/2018-0006