

Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2010-0213** - AIRBUS HELICOPTERS DEUTSCHLAND: SUPERSEDED BY EASA AD 2017-0002

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2010-0213>

* **AD 2016-0071** - EADS CASA: SUPERSEDED BY EASA AD 2017-0004

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2016-0071>

* **AD 2017-0004** - EADS CASA: Fuel – Motorised Fuel Valve – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0004>

* **AD 2017-0003** - ROLLS-ROYCE PLC: Engine – Compressor Intermediate Case – Inspection / Repair

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0003>

* **AD 2017-0002** - AIRBUS HELICOPTERS DEUTSCHLAND: Main Rotor Drive – Main Transmission Housing Upper Part – Modification

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2017-0002>

* **SIB 2016-19R1** - Safety Information Bulletin: Honeywell Mode S Transponders: Enhanced Surveillance Parameters not provided to Mode S Ground Stations

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2016-19R1>