

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD** US-2018-14-08 - BOEING: Fuel - Operating Limitations - Revision

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/US-2018-14-08>

---

\* **AD** 2018-0156 - LEONARDO S.p.A. HELICOPTERS: Tail Rotor Drive – Gearbox Output Shaft – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0156>

---

\* **SIB** 2018-11 - Safety Information Bulletin: Engine Fire Extinguishing - Wire Chafing in Pylon

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-11>

---