

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD** US-2018-14-01 - PIPER AIRCRAFT INC.: AFM Change / Placard Installation – Cockpit Area Fuselage Skin – Inspection / Repair

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/US-2018-14-01>

---

\* **PAD** 18-093 - AIRBUS: Fuselage – Cargo Compartment Fitting Brackets, Tack and Rivet Holes – Inspection / Repair

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/18-093>

---