

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD 2018-0123** - AIRBUS: Fuselage – Tail Cone Balancer Fitting Anchor Nuts and Fasteners – Modification

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0123>

---

\* **AD 2018-0111R1** - AIRBUS: Water/Waste – Forward Fuselage Shrouded Pipe T-Boxes and Clamps – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0111R1>

---

\* **AD 2018-0122** - FOKKER SERVICES: Placards and Markings – Auxiliary Power Unit Air Intake – Introduction

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0122>

---

\* **AD 2018-0112R1** - LEONARDO S.p.A. HELICOPTERS: Main Rotor – Main Rotor Damper – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0112R1>