

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD DCA-750XL-29** - PACIFIC AEROSPACE LTD: Refrigerant Hose Insulation – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/DCA-750XL-29>

---

\* **AD DCA-750XL-30** - PACIFIC AEROSPACE LTD: Relocation of Ground Terminations – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/DCA-750XL-30>

---

\* **AD DCA-750XL-31** - PACIFIC AEROSPACE LTD: Firewall Wiring Penetrations – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/DCA-750XL-31>

---

\* **PAD 18-089** - AIRBUS HELICOPTERS: Main Rotor Blade Attachment Pin – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/18-089>

---

\* **EAD 2018-0140-E** - AIRBUS HELICOPTERS: Equipment & Furnishings - Hoist - Removal; Cabin Sliding Plug Doors / Emergency Jettisoning System - Rotorcraft Flight Manual Amendment / Placard Installation

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0140-E>