

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2011-0168R1** - AIRBUS HELICOPTERS DEUTSCHLAND: Lights – Instrument Lighting Display Brightness – Modification

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2011-0168R1>

* **AD US-2012-12-05** - BOEING: SUPERSEDED BY FAA AD 2018-04-06

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2012-12-05>

* **AD US-2018-04-06** - BOEING: Fuselage - Forward Entry Door Cut-out Intercostals / Frame Inner Chord – Inspection / Repair

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2018-04-06>

* **AD US-2018-06-05** - BOEING: Wings - Lower Wing Skin - Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/US-2018-06-05>