

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD 2018-0244** - AIRBUS: Flight Controls – Flap / Slat Torque Shafts – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0244>

---

\* **AD 2018-0245** - AIRBUS: Oxygen – Crew Oxygen Cylinder Regulator – Operational Check / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0245>

---

### **IMPORTANT NOTICE**

The 6th EASA Airworthiness Directives (AD) Workshop will be held on **20-21 November 2018** in Cologne.

The event is addressed to all interested stakeholders such as operators, CAMO, maintenance organisations, design approval holders, who want to have a better understanding of EASA processes related to safety publications.

More information, agenda and online registration are available [here](#).

EASA Safety Information Section