The following Documents have been published or updated by EASA and may be of interest to you:

\* **PAD** 18-163 - AIRBUS: Fuselage – Lateral Cockpit Window Frame Upper Stiffener – Inspection

TO see the details OF this Publication, please click OR copy the following: URL: http://ad.easa.europa.eu/ad/18-163

TO see the details OF this Publication, please click OR copy the following: URL: <a href="http://ad.easa.europa.eu/ad/18-162">http://ad.easa.europa.eu/ad/18-162</a>

<sup>\*</sup> PAD 18-162 - AIRBUS: Wings - Flaps - Inspection / Replacement [Wrong Material]