

The following Documents have been published or updated by EASA and may be of interest to you:

\* **EAD** US-2018-23-51 - BOEING: Airplane Flight Manual - Runaway Horizontal Stabilizer Trim Limitations / Procedures - Amendment

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/US-2018-23-51>

---

\* **PAD** 18-150 - ENSTROM HELICOPTER CORPORATION: Main Rotor – Hydraulic Damper / Belt Tension Shaft Rod End Assembly – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/18-150>

---

### **IMPORTANT NOTICE**

The 6th EASA Airworthiness Directives (AD) Workshop will be held on **20-21 November 2018** in Cologne.

The event is addressed to all interested stakeholders such as operators, CAMO, maintenance organisations, design approval holders, who want to have a better understanding of EASA processes related to safety publications.

More information, agenda and online registration are available [here](#).

EASA Safety Information Section