

The following Documents have been published or updated by EASA and may be of interest to you:

\* **PAD 18-144 - AIRBUS HELICOPTERS: Tail Rotor – Hub Assembly – Replacement**

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/18-144>

---

### **IMPORTANT NOTICE**

The 6th EASA Airworthiness Directives (AD) Workshop will be held on **20-21 November 2018** in Cologne.

The event is addressed to all interested stakeholders such as operators, CAMO, maintenance organisations, design approval holders, who want to have a better understanding of EASA processes related to safety publications.

More information, agenda and online registration are available [here](#).

EASA Safety Information Section