

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD** 2017-0137 - LEONARDO S.p.A. HELICOPTERS: SUPERSEDED BY EASA AD 2018-0203

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2017-0137>

---

\* **AD** 2018-0203 - LEONARDO S.p.A. HELICOPTERS: Rotors Flight Control – Pilot Collective Stick Assembly – Check

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0203>

---

\* **SIB** 2018-17 - Safety Information Bulletin: Liquid Penetrant Inspection / Use of Visible Dye Penetrant

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-17>

---

\* **SIB** NE-18-27 - Safety Information Bulletin: Continental Motors Inc. (incl. RR Continental) - Engine Rocker Shaft Boss Inspection

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/NE-18-27>

---

### **IMPORTANT NOTICE**

The 6th EASA Airworthiness Directives (AD) Workshop will be held on **20-21 November 2018** in Cologne.

The event is addressed to all interested stakeholders such as operators, CAMO, maintenance organisations, design approval holders, who want to have a better understanding of EASA processes related to safety publications.

More information, agenda and online registration are available [here](#).

EASA Safety Information Section