

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD 2018-0206** - AIRBUS HELICOPTERS: Main Rotor – Mast Upper Bearing Sealant Bead / Inner Race Retaining Rings – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0206>

---

\* **AD 2018-0208** - LEONARDO S.p.A. HELICOPTERS: Emergency Flotation System – Aft Float Assembly Inflation System – Removal / Installation

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0208>

---

\* **AD US-2018-19-04** - LEARJET, INC.: Flight Controls - Flap Nose Roller Fitting, Nose Roller Support Bracket, and Adjacent Rib Support Structure - Replacement

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/US-2018-19-04>

---

### **IMPORTANT NOTICE**

The 6th EASA Airworthiness Directives (AD) Workshop will be held on **20-21 November 2018** in Cologne.

The event is addressed to all interested stakeholders such as operators, CAMO, maintenance organisations, design approval holders, who want to have a better understanding of EASA processes related to safety publications.

More information, agenda and online registration are available [here](#).

EASA Safety Information Section