

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** 2018-0196 - AIRBUS: Flight Controls – Flight Control Primary Computer – Modification / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0196>

* **AD** 2018-0188R1 - ROLLS-ROYCE PLC: Engine – Low Pressure Compressor Blades – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0188R1>

* **AD** 2018-0197 - LEONARDO S.p.A. HELICOPTERS: Windows – Emergency Exit Windows – Modification

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0197>

* **PAD** 18-121 - AIRBUS: Time Limits / Maintenance Checks – Airworthiness Limitations Section Part 5 – Fuel Airworthiness Limitations - Amendment

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/18-121>

IMPORTANT NOTICE

The 6th EASA Airworthiness Directives (AD) Workshop will be held on **20-21 November 2018** in Cologne.

The event is addressed to all interested stakeholders such as operators, CAMO, maintenance organisations, design approval holders, who want to have a better understanding of EASA processes related to safety publications.

More information, agenda and online registration are available [here](#).

EASA Safety Information Section