

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD** 2018-0168 - AIRBUS HELICOPTERS DEUTSCHLAND: Tail Rotor – Blade – Re-identification / Life Limit

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-0168>

* **PAD** 18-108 - ROLLS-ROYCE DEUTSCHLAND: Engine – High Pressure Turbine Stage 1 Turbines Blades and Blade Damper – Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/18-108>

* **PAD** 18-109 - AIRBUS HELICOPTERS: Rotor Drive – Main Gearbox Magnetic Plugs – Inspection

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/18-109>

* **SIB** 2018-12 - Safety Information Bulletin: Post de-icing/anti-icing checks

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2018-12>