

Occurrence Communication: Oc00234-2018 **Date:** 21/Aug/2018

Page 1 of 1

Type: /

Aircraft: EMB-145	Model: EMB-145 XR	Serial Number: 145719
Marks: N12136	Operator: TRANS STATES	Occurrence Date: 09/Jul/2018
Ata: 72	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: NOT AVAILABLE		
Injuries: <input checked="" type="checkbox"/> None Light: 0 Serious: 0 Fatal: 0		

Occurrence Description:

Report of abnormal odor and smoke in the cabin
The flight crew reported abnormal odor and smoke in the cabin.

Maintenance personnel removed and replaced the suspected engine.

ADDITIONAL INFORMATION:

Rolls-Royce identified the engine carbon seal #0 as the root cause of the smoke and odor.