

Occurrence Communication: Oc00241-2018 **Date:** 23/Aug/2018

Page 1 of 1

Type: /

Aircraft: EMB-145	Model: EMB-145 MP	Serial Number: 145266
Marks: C9-MEX	Operator: MOZAMBIQUE	Occurrence Date: 20/Aug/2018
Ata: 72	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: BEIRA - BEIRA - MOZAMBIQUE		
Injuries: <input checked="" type="checkbox"/> None Light: 0 Serious: 0 Fatal: 0		

Occurrence Description:

Report of precautionary engine 2 IFSD due to engine low oil level indication
The flight crew reported an engine 2 low oil quantity indication during cruise. They then performed a precautionary engine 2 IFSD. An uneventful single engine landing was performed at destination airport.

Maintenance personnel removed and replaced the engine 2 in order to investigate the oil leakage. The aircraft was returned to service with no further issues.