

## EMBRAER S.A.

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901 Phone: +55 12 3927-2568 / -8924 Fax: +55 12 3927-1184

**Occurrence Communication:** Oc00261-2018 **Date:** 17/Sep/2018 Page 1 of 1

**Type: Major Event** 

Aircraft:	Mode	el:	Serial Number:
EMB-145	EMB-	145 LU	1451070
Marks:	Opera	ator:	Occurence Date:
9G-AFI	AFRI	CA WORLD	25/Jul/2018
Ata: 72 Time:		Number of Persons Aboard: Not Available	
Aircraft Damages:	I		1
Aircraft Damages:	·		I
Aircraft Damages:  Site: NNAMDI AZIKIWE INTL	- ABUJA - NIGERI	IA	I
Site:	- ABUJA - NIGER Light: 0	IA Serious: <sup>0</sup>	Fatal: 0

The flight crew reported "E1 LOW N1" warning message on EICAS and engine 1 ITT showing dashes during takeoff. They then elected to abort the takeoff. On the way back to the gate, they experienced an uncommanded engine 1 OGSD.

Maintenance personnel identified damages on the high pressure compressor and removed and replaced the engine 1.