

EMBRAER S.A.

Av. Brig. Faria Lima, 2170, São José dos Campos - SP - Brasil, 12227-901 Phone: +55 12 3927-2568 / -8924 Fax: +55 12 3927-1184

Occurrence Communication:

Oc00312-2018 Date: 20/Nov/2018

Page 1 of 1

Type: /

Aircraft:	Model:	Serial Number:
EMB-505	EMB-505	5050468
Marks:	Operator:	Occurence Date:
N423QS	NetJets Sales, Inc.	14/Nov/2018
Ata: 53	Time:	Number of Persons Aboard: Not Available
Aircraft Damages:		
Site: FOUR CORNERS REGL - FARMINGTON - NM - UNITED STATES		
Injuries: X None Light:	0 Serious: 0 F	Fatal: ⁰

Occurence Description:

Report of abnormal vibration during descent

The flight crew reported an abnormal vibration during descent at around FL250 and 300 knots. Maintenance personnel inspected the airframe and found some wing-to-fuselage fairings seals eroded and loose, which were resecured.