

22 March 2018



Continuing Airworthiness Sections
National Civil Airworthiness Authorities
ICAO Contracting States

Notification of Airworthiness Directive issued for New Zealand Aeronautical Products IAW ICAO Annex 8.

The following Airworthiness Directive is issued by the New Zealand Civil Aviation Authority who is the responsible state of design national airworthiness authority for the product in accordance with ICAO Annex 8.

DCA/750XL/25A Wing Leading Edge Tank Abrasion - Inspection

This AD with effective date 22 March 2018 mandates the instructions in Pacific Aerospace Limited Mandatory Service Bulletin (MSB) PACSB/XL/091 issue 3, dated 15 March 2018.

The Pacific Aerospace MSB revised to include additional repair information. The MSB is issued to prevent abrasion damage to the wing leading edge. Chafing by the ventilation duct could result in a fuel leak.

A copy of DCA/750XL/25A is attached. NZ ADs applicable to 750XL aircraft are available from the CAA web site at

http://www.caa.govt.nz/assets/legacy/Airworthiness_Directives/750XL.pdf

Yours faithfully

A handwritten signature in black ink, appearing to read 'Owen Olls', is written over a faint, light-colored circular stamp or watermark.

Owen Olls
Airworthiness Specialist

Phone +64 4 560 9569 UTC + 12
Fax +64 569 2024
owen.olls@caa.govt.nz