

28 June 2018



Continuing Airworthiness Sections  
National Civil Airworthiness Authorities  
ICAO Contracting States

**Notification of Airworthiness Directive issued for New Zealand Aeronautical Products IAW ICAO Annex 8.**

The following Airworthiness Directive is issued by the New Zealand Civil Aviation Authority who is the responsible state of design national airworthiness authority for the product in accordance with ICAO Annex 8.

**DCA/750XL/29 Refrigerant Hose Insulation – Inspection**

Air Transport Association (ATA) Chapter 21, Air Conditioning.

The insulation lagging provided by the air-conditioning supplier has been found to be non-compliant and may cause large amounts of smoke in the cabin in the event of a fire. DCA/750XL/29 issued to mandate the instructions in Pacific Aerospace Mandatory Service Bulletin (MSB) PACSB/XL/086 issue 2, dated 6 April 2018, or later approved revision to correct non-compliant insulation lagging on the refrigerant hoses of the air-conditioning system.

A copy of DCA/750XL/29 is attached. NZ ADs applicable to 750XL aircraft are available from the CAA web site at

[http://www.caa.govt.nz/assets/legacy/Airworthiness\\_Directives/750XL.pdf](http://www.caa.govt.nz/assets/legacy/Airworthiness_Directives/750XL.pdf)

Yours faithfully

A handwritten signature in black ink, appearing to read 'Owen Olls', is written over a light grey rectangular stamp.

Owen Olls  
Airworthiness Specialist

Phone +64 4 560 9569 UTC + 12

Fax +64 569 2024

[owen.olls@caa.govt.nz](mailto:owen.olls@caa.govt.nz)