

28 June 2018



Continuing Airworthiness Sections
National Civil Airworthiness Authorities
ICAO Contracting States

Notification of Airworthiness Directive issued for New Zealand Aeronautical Products IAW ICAO Annex 8.

The following Airworthiness Directive is issued by the New Zealand Civil Aviation Authority who is the responsible state of design national airworthiness authority for the product in accordance with ICAO Annex 8.

DCA/750XL/31 Firewall Wiring Penetrations – Inspection

Air Transport Association (ATA) Chapter 71, Power Plant - General.

During a review of the installation of the aircraft main loom P/N 11-81021, possible ineffective sealing was identified for firewall wiring penetrations. DCA/750XL/31 is issued to mandate the instructions in Pacific Aerospace Mandatory Service Bulletin (MSB) PACSB/XL/101 issue 1, dated 9 May 2018, or later approved revision, to improve the firewall sealing by installing new components (firewall penetration tubes, firesleeve and hose clips).

A copy of DCA/750XL/31 is attached. NZ ADs applicable to 750XL aircraft are available from the CAA web site at

http://www.caa.govt.nz/assets/legacy/Airworthiness_Directives/750XL.pdf

Yours faithfully

A handwritten signature in black ink, appearing to read 'Owen Olls', is written over a light grey rectangular stamp area.

Owen Olls
Airworthiness Specialist

Phone +64 4 560 9569 UTC + 12

Fax +64 569 2024

owen.olls@caa.govt.nz