

Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

* **AD 2006-0134** - ASI AVIATION: SUPERSEDED BY EASA AD 2019-0015

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2006-0134>

* **AD 2015-0159R1** - ASI AVIATION: SUPERSEDED BY EASA AD 2019-0016

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2015-0159R1>

* **AD 2016-0172** - AIRBUS: SUPERSEDED BY EASA AD 2019-0014

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2016-0172>

* **AD 2019-0014** - AIRBUS: Electrical Power – Wing Electrical Installation – Modification

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2019-0014>

* **AD 2019-0015** - ASI AVIATION: Electrical Power – Circuit Breaker Switches – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2019-0015>

* **AD 2019-0016** - ASI AVIATION: Flight Controls – Rudder Control Pedal Torque Tubes – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:
<http://ad.easa.europa.eu/ad/2019-0016>