

Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD** 2017-0020R1 - AIRBUS HELICOPTERS: Tail Rotor “ Pitch Rod “ Inspection

TO see the details OF this Publication, please click OR copy the following: URL:

<http://ad.easa.europa.eu/ad/2017-0020R1>

---

\* **AD** CF-2019-21 - BOMBARDIER: Wing Structure “ Lower Wing Plank “ Cracking at Stringer Run-out

TO see the details OF this Publication, please click OR copy the following: URL:

<http://ad.easa.europa.eu/ad/CF-2019-21>