

Dear Subscriber,

The following Documents have been published or updated by EASA and may be of interest to you:

\* **AD** 2017-0226 - AIRBUS HELICOPTERS: SUPERSEDED BY EASA AD 2019-0088

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2017-0226>

---

\* **AD** 2018-0075 - GE AVIATION CZECH: SUPERSEDED BY EASA AD 2019-0089

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2018-0075>

---

\* **AD** 2019-0088 - AIRBUS HELICOPTERS: Placards and Markings – Inspection / Installation

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2019-0088>

---

\* **PAD** 19-072 - AIRBUS: Fuselage – Forward Cargo Door Upper Frame Fittings and Brackets – Inspection / Modification

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/19-072>

---

\* **PAD** 19-073 - AIRBUS: Fuselage – Structure Frames and Joints – Modification / Reinforcement

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/19-073>

---

\* **AD** 2019-0089 - GE AVIATION CZECH: Engine Controls – Push-Pull Control and Beta Switch – Inspection / Replacement

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/2019-0089>

---

\* **PAD** 19-074 - AIRBUS: Wings – Centre Wing Box Fastener Holes at Frame 40 Vertical Web – Inspection / Modification

TO see the details OF this Publication, please click OR copy the following: URL:  
<http://ad.easa.europa.eu/ad/19-074>

